

LSJE, LLC

6100 Red Hook Quarters, Suite B-3, St. Thomas, VI 00802-1348
Phone: 340-775-2525 E-mail: [REDACTED]

Check Request Form

Date of Request:	11/14/18	Amount Requested:	\$9,000.00
Payee:	B.V.I. Painters Ltd	Payee Address:	PO Box 824 Road Town Tortola British Virgin Islands
Payee Contact:	[REDACTED]		

☐ Check box if GL coding is split


Invoice N./Memo:	Est 3094	GL Memo:	50% deposit to begin work - raise engine bracket, interior and exterior paint job
GL Description:	Nautica		
GL Code:	60252n		
GL Amount:	\$9,000.00		

Invoice N./Memo:		GL Memo:	
GL Description:			
GL Code:			
GL Amount:			

☐ Check box if additional pages are included

Other Notes/
Instructions:

Requesting local check. Transportation to BVI scheduled for 11/20/18, contingent on Little C engine install going smoothly 11/19/18. Completion date contingent on weather.

Date Approved:	11/14/18
Approved by:	



B.V.I. Painters Ltd
P.O. Box 824,
Road Town, Tortola
British Virgin Islands.
Tel: 284 494 4365
[Redacted]

Estimate

Date	Estimate No.
11/10/18	3094

Name/Address
Nautica RIB
Little Saint James

Description	Quantity	Cost	Total
Labour and Material cost estimate to:			0.00
1.) Remove and reinstall engine		0.00	0.00
. Raise engine Bracket (owner will provide specs for engine bracket)			
2. Repair area from inspection cut			0.00
. Prep area and manufacture new pieces to fill holes			
. Inspection holes must be cut in a 40 degree angle to fit manufactured pieces			
3. Interior Floor			0.00
. Remove soft decking			
. Inspect and repair damage areas			
. Fill and Fair			
. Tape and mask			
. Spray two coats of primer			
. Sand primer			
. Apply two coats of top coat			
. Sand			
. Change tape			
. Apply two more coats of top coat			
. Tape off smooth Areas and apply two coats in non-skid area with silicone beads			
4. Topside:- From the waterline to the toe rail			0.00
. Repairs/cover holes from bow railing			
. Sand entire topside			
. Fill and fair			
. Tape and mask			
. Spray two coats of primer			
50% deposit before start balance due on completion.			
		Total	



B.V.I. Painters Ltd
P.O. Box 824,
Road Town, Tortola
British Virgin Islands.
Tel: 284 494 4365
[Redacted]

Estimate

Date	Estimate No.
11/10/18	3094

Name/Address
Nautica RIB Little Saint James

Description	Quantity	Cost	Total
. Sand Primer			
5. Bottom- Below waterline			0.00
. Sand entire bottom			
. Prep any damage areas and fair with epoxy filler			
. Sand			
. Apply inter protect where necessary			
. Then apply two coats of Antifouling			
6. Repaint engine covers			0.00
Estimated labour and material cost to complete the above mention Jobs		18,000.00	18,000.00
Please note that this is only an estimate			
50% deposit before start balance due on completion.		Total	\$18,000.00