

From: J <jeevacation@gmail.com>

To: Eric Roth <[REDACTED]>, Ivjet <[REDACTED]>

Subject: Re: G550 Next Week

Date: Fri, 15 Mar 2019 13:43:13 +0000

Inline-Images: image001.jpg; image002.jpg; image003.jpg

I will arrive New York Sunday and leave tues early. If you would you have the foam and fabric if not too much trouble we could test as you suggest. U have been very accommodating . If it works i can give you the plane april 1

On Fri, Mar 15, 2019 at 9:38 AM Eric Roth <[REDACTED]> wrote:

Jeffrey,

We spoke with Larry yesterday regarding your schedule / our schedule and what we can accomplish / when.

Larry noted that you will be coming to New York and that he could bring the aircraft here Monday morning for a few days until your trip to Paris.

Although we are jammed up at the moment in our upholstery shop, we did suggest that we replace the foam in the divan mattress as well as one of the single seat cushions with your "new foam", providing the opportunity for you to "test" the new foam on your long trip to insure that you do not want to make any additional changes to the density of the foam layup. I believe this trip to France would provide you an ideal amount of time / situations to really get a feel for your level of comfort and satisfaction.

In addition, we could start to knock off a few (no upholstery) items from the list below.

Kindly let us know your thoughts so that we can prepare for Monday.

Thank you.

1. Fwd L/H Bulkhead Monitor Closeout

Fabricate wood handle and finish to replace existing clear vinyl tab

2. Fwd R/H Cabin Bulkhead

Fabricate temporary cover for Exit Sign in wood veneer to complement existing

3. Fwd Cabin Pocket Door

Camouflage door handle and create visual symmetry of seam(s). Fabricate rectangle veneer with top of piece at same elevation as top of L/H bulkhead monitor opening. Lower horizontal line could be at top of seat back height. Overall width approx. 5.0"

4. Mid Cabin Curtain

Fabricate new one? Sew vertical seams in existing to help minimize the wrinkles at the bottom? Need additional retaining strip with metal plated snaps.

5. Monitor on Ledge

New monitor (in the color black) with swing arm mounted to ledge?

6. Speaker Bar

Mounted above side duct outboard of lower side panel? Incorporate speaker grill to allow acoustic transmissivity?

7. Sub-Woofer

What are we doing with Carry On sub-woofer?

8. Divan Arm rests & Doors & Close Outs

Add (.50" ?) foam to inboard vertical and top of arms (to be "softer")?

Reupholster arm rests in Crate and Barrel fabric?

Reupholster divan doors in Crate and Barrel fabric?

Reupholster lower close outs in Crate and Barrel fabric?

Reupholster fwd arm rest removable half bulkhead in Crate and Barrel fabric?

9. Divan "Carry On" mattress

Reupholster in new Crate and Barrel fabric – make softer

10. Aft Galley / Lavatory door

Replace double stick tape with contact adhesive on wood veneer closeout for horizontal piece.

11. Aft R/H Galley

Replace double stick tape with contact adhesive on wood veneer closeout for aft bulkhead piece.

12. Aft Lavatory Potty Seat

Cut and sew white fabric pad in half

13. Aft Lavatory Toilet Paper Door

Work "garage door" so that it is more stable when being open or closed

14. Aft L/H Galley

Replace existing LED lights with new both inside the glass rack compartment and underneath that illuminates the countertop.

15. Aft Galley

Fabricate inserts to contain customer supplied carry on items.

16. Foot Stool

Fabricate a second foot stool (covered in carpet to match the existing) so that they both fit into the existing “bag dock” on the L/H mid cabin

17. Sidewall Table Pulls

Hard edges are uncomfortable against fingers. Cover edge in leather / rubber / trim this piece for comfort

continued

18. Aft Lavatory Door

“Hinge” on door makes noise

19. Single seats

Fabricate 2 single seat fabricate two (2) bottom seat cushions employing the same type (non fireblock) of foam that you used on the divan mattress. Please Upholster the cushions in leather to match the seat.

20. table springs?

21. top adjusted?

22. bag holder. redone.

23. new top for credenza or we can make seat. ?

24. veneer needs attention. in a couple of places. .

25. need to rethink coffee compartment to remove steam. .

Best Regards,

Eric

ERIC H. ROTH | PRESIDENT

 IJI Logo - Horizontal-SMALL

P [REDACTED] C [REDACTED] [REDACTED] www.intljet.com  

[2221 Smithtown Avenue, Long Island](#) MacArthur Airport, Ronkonkoma, New York 11779

--

please note

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of JEE

Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to jeevacation@gmail.com, and destroy this communication and all copies thereof, including all attachments. copyright -all rights reserved